

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(RE. G.O. 20/70/PWD DT. 23 - 01 - 1970)

1. Name of the Officer

Mr. Madan Puri

2. Name of the School

Anand's Academy Bageshwar

3. Location with name of

Vill/P.O. - Ehiroli Distt - Bageshwar

Education District/Sub, District

4. Classification of Building as

C.R.F., Hall - 1, office - 1, Class rooms - 17

specified in column 4 of the application for fitness certificate and size.

Play Ground - 1, Boundary wall as per school rooms.

5. Period for which the certificate is issued

5 years

6. Nature of defects. If any

No. defect

a) Foundation and basement

No. Defect

b) Superstructure

No. Defect

c) Doors and Windows

No. Defect

d) Wood work wrought and put up

No. Defect

e) Roof

No. Defect

g) Miscellaneous (Cracks, etc.)

None

7. Any major defects noticed which will render the building unsafe in any manner

No.

None

8. Whether maintenance works have been done properly

Yes

9. Whether the structure is sound or not for conducting classes

No. sounding, Good for conducting classes

Note:- The stability of the structure should be examined also with reference to location. Altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

Certified that the school building was inspected by me on 19/2/2019 and found to be fit/unit to conduct classes, for the period 5 years for the reasons stated above.

Place: Bageshwar

Date: 19/2/2019

(Seal)

Assistant Engineer
Construction Unit

Mr. Madan Puri
Assistant Engineer