

02/2019

FITNESS CERTIFICATE

To be filed by the Inspecting Officer (Asst. Engineer)

(RE. G.O. 20/70/PWD DT. 23 - 01 - 1970)

1. Name of the Officer Mr Madan Puri
2. Name of the School Anandi Academy Bageshwar
3. Location with name of Education District/Sub, District Vill/PO - Ghiroli Distt - Bageshwar
4. Classification of Building as specified in column 4 of the application for fitness certificate and size. C.E. Hall - 1 office - 1, Class rooms - 17
Play Ground - 1, Boundary wall as per school rooms,
5. Period for which the certificate is issued 5 years
6. Nature of defects. If any
 - a) Foundation and basement No. Defect
 - b) Superstructure No. Defect
 - c) Doors and Windows No. Defect
 - d) Wood work wrought and put up No. Defect
 - e) Roof No. Defect
 - g) Miscellaneous (Cracks, etc.) None.
7. Any major defects noticed which will render the building unsafe in any manner No.
None
8. Whether maintenance works have been done properly Yes
9. Whether the structure is sound or not for conducting classes No. Sounding, Good for conducting classes


Note:- The stability of the structure should be examined also with reference to location. Altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this Certificate.

CERTIFICATE

Anandi Academy
Ghiroli (Bageshwar)

Certified that the school building was inspected by me on 19/2/2019 and found to be fit/unit to conduct classes, for the period 5 years for the reasons stated above.

Place: Bageshwar
Date: 19/2/2019



Madan Puri
Assistant Engineer
Manager
Anandi Academy
Ghiroli (Bageshwar)