

Annexure D

BUILDING SAFETY CERTIFICATE

No. 2491/2023-24

Dated: 19/2/2024

It is certified that the existing building Anandi Academy (name of the building or premises) at Vill. / PO. - CHIROLI, DISTT - BAGESHWAR (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	<u>GROUND, 1, 2, 3</u>					

The building is owned/occupied by Anandi Academy (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of (Name of Department/ Govt.) on 17/02/2024 (date of inspection) in the presence of Manmohan Singh Bhatuni (Manager) Anandi Academy (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 19/2/2024 for a period of 5 years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 19/2/2024 at Bageshwar by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal

सहायक अभियन्ता

Name SUNIL SINGH DATTAL

Designation : A.E R.W.D

Name & Address of Department/ Office: RURAL WORKS DEPARTMENT